



Airworthiness Directive

AD No.: 2026-0137

Issued: 10 July 2026

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

PIPISTREL VERTICAL SOLUTIONS d.o.o.

Type/Model designation(s):

Virus SW 121 and SW 128 aeroplanes

Effective Date: 24 July 2026

TCDS Number(s): EASA.A.573

Foreign AD: Not applicable

Supersedure: None

ATA 52 – Doors – Door Locking Mechanism – Modification

Manufacturer(s):

Pipistrel d.o.o.

Applicability:

Virus SW 121, Virus SW 121A, Virus SW 121C, Virus SW 121X, Virus SW 128 aeroplanes, all serial numbers (s/n).

Definitions:

For the purpose of this AD, the following definitions apply:

The SB: Pipistrel Vertical Solutions d.o.o. (PVS) Service Bulletin (SB) SB-121-00-80-040 Revision A01.

Groups: Group 1 aeroplanes are Virus SW 121 aeroplanes, all s/n, Virus SW 121A aeroplanes s/n up to VSW121A0198 inclusive, Virus SW 121C aeroplanes s/n up to VSW121C0180 inclusive, Virus SW 121X aeroplanes s/n up to VSW121X0121 inclusive and Virus SW 128 aeroplanes s/n up to VSW1280119 inclusive, and s/n from VSW1280151 to VSW1280154 inclusive.

Group 2 aeroplanes are those that are not Group 1 aeroplanes.

Reason:

Occurrences of in-flight door detachment were reported. Subsequent investigation identified wear in the locking pin.



This condition, if not corrected, could lead to an in-flight door opening, possibly resulting in damage to the aeroplane and injury to persons on the ground.

To address this potential unsafe condition, PVS issued the SB to provide instructions for modification of the door locking mechanism.

For the reasons described above, this AD requires modification of the door locking mechanism.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

Modification:

- (1) For Group 1 aeroplanes: Within 100 flight hours or 60 days, whichever occurs first after the effective date of this AD, modify the locking mechanism of the left-hand (LH) and right-hand (RH) door in accordance with the instructions of the SB.

Credit:

- (2) Modification of a door locking mechanism accomplished before the effective date of this AD in accordance with the instructions of PVS SB-121-00-80-040 at original issue, is acceptable to comply with the requirements of paragraph (1) of this AD for that aeroplane, as applicable.

Part(s) Installation:

- (3) For Group 1 and Group 2 aeroplanes: From the effective date of this AD, it is allowed to (re)install a door (LH or RH) locking mechanism, on an aeroplane, provided that it complies with the requirements of this AD (see Note 1 of this AD).

Note 1: Door locking mechanism delivered as spare by PVS with an EASA Form 1 (or equivalent Statement of Conformity) dated after 15 December 2025, or initially installed in production on Group 2 aeroplanes, are compliant with the requirements of this AD.

- (4) For Group 1 and Group 2 aeroplanes: From the effective date of this AD, it is allowed to (re)install a door (LH or RH) on an aeroplane, provided that it is equipped with the locking mechanism which complies with the requirements of this AD (see Note 1 of this AD).

Ref. Publications:

SB-121-00-80-040 original issue dated 15 December 2025, and Revision A01 dated 10 July 2026.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.



All interested persons may send their comments, referencing the AD Number, to the E-mail address specified in below Remark 3, prior to 07 August 2026. Only if any comment is received during the consultation period, a Comment Response Document will be published in the [EASA Safety Publications Tool](#), in a compressed ('zipped') file, attached to the record for this AD.

3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: Pipistrel Vertical Solutions d.o.o. Vipavska cesta 2, 5270 Ajdovščina, Slovenia; E-mail: maintenance@pipistrel.si.



TRADUCTION DE COURTOISIE

de la DIRECTIVE de NAVIGABILITE de l'EASA de référence 2026-0137

PIPISTREL VERTICAL SOLUTIONS d.o.o.

Avions Virus SW 121 et SW 128

Portes – Mécanisme de verrouillage des portes – Modification

DATE D'ENTREE EN VIGUEUR :

24 Juillet 2026

CONSTRUCTEUR(S) :

Pipistrel d.o.o.

APPLICABILITE :

Avions Virus SW 121, Virus SW 121A, Virus SW 121C, Virus SW 121X et Virus SW 128, tous numéros de série (s/n).

DEFINITIONS :

Les définitions suivantes s'appliquent dans le cadre de cette CN :

Le SB : Bulletin de service (SB) SB-121-00-80-040, révision A01, de Pipistrel Vertical Solutions d.o.o. (PVS).

Groupes : Les avions du groupe 1 sont les Virus SW 121, tous numéros de série confondus, les Virus SW 121A jusqu'au numéro VSW121A0198 inclus, les Virus SW jusqu'au numéro VSW121C0180 inclus, les avions Virus SW 121X jusqu'au numéro VSW121X0121 inclus, ainsi que les avions Virus SW 128 jusqu'au numéro VSW1280119 et ceux dont le numéro de série est compris entre VSW1280151 et VSW1280154 inclus.

Les avions du groupe 2 sont ceux qui n'appartiennent pas au groupe 1.

RAISON :

Des cas d'ouverture de portes en vol ont été signalés. L'enquête menée par la suite a mis en évidence une usure de la goupille de verrouillage

Si elle n'est pas corrigée, cette anomalie pourrait entraîner l'ouverture de la porte en vol, ce qui pourrait causer des dommages à l'avion et blesser des personnes au sol.

Afin de remédier à cette anomalie potentiellement dangereuse, PVS a publié le SB fournissant des instructions pour la modification du mécanisme de verrouillage de la porte.

Pour les raisons décrites ci-dessus, cette CN impose la modification du mécanisme de verrouillage de la porte.

ACTIONS ET DELAIS D'APPLICATION :

Requises telles que précisées dans cette CN, sauf si ces actions requises par cette CN ont déjà été réalisées :

Modification :

(1) Pour les avions du groupe 1 : dans un délai de 100 heures de vol ou de 60 jours, selon la première échéance après la date d'entrée en vigueur de cette CN, modifier le mécanisme de verrouillage des portes gauche (LH) et droite (RH) conformément au SB.

Crédit :

(2) Une modification du mécanisme de verrouillage d'une porte effectuée avant la date d'entrée en vigueur de cette CN, conformément aux instructions du SB PVS SB-121-00-80-040 dans sa version initiale, est considérée comme satisfaisant aux exigences du paragraphe (1) de cette CN pour cet avion, le cas échéant.

Installation des pièces :

(3) Pour les avions des groupes 1 et 2 : à compter de la date d'entrée en vigueur de cette CN, il est autorisé d'installer ou de réinstaller un mécanisme de verrouillage de porte (gauche ou droite) sur un avion, à condition qu'il soit conforme aux exigences de cette CN (voir la note 1 de cette CN).

Note 1 : Les mécanismes de verrouillage de porte livrés en pièce de rechange par PVS avec un formulaire 1 de l'EASA (ou une déclaration de conformité équivalente) daté d'après le 15 décembre 2025, ou installés d'origine lors de la production sur des avions du groupe 2, sont conformes aux exigences de cette CN.

(4) Pour les avions des groupes 1 et 2 : à compter de la date d'entrée en vigueur de cette CN, il est autorisé de (ré)installer une porte (gauche ou droite) sur un avion, à condition qu'elle soit équipée d'un mécanisme de verrouillage conforme aux exigences de la présente consigne de navigabilité (voir la note 1 de cette CN).

DOCUMENTS DE REFERENCE:

SB-121-00-80-040, version originale datée du 15 décembre 2025, et révision A01 datée du 10 juillet 2026.

L'utilisation de révisions approuvées ultérieurement des documents susmentionnés est acceptable pour la conformité aux exigences de la présente CN.

REMARQUES :

[...]