



Emergency Airworthiness Directive

AD No.: 2026-0191-E

Issued: 02 October 2026

Note: This Emergency Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

ELIXIR AIRCRAFT

Type/Model designation(s):

Elixir aeroplanes

Effective Date: 03 October 2026

TCDS Number(s): EASA.A.633

Foreign AD: Not applicable

Supersedure: None

ATA – SUSPENSION OF FLIGHT OPERATIONS

Manufacturer(s):

ELIXIR AIRCRAFT (ELIXIR)

Applicability:

ELIXIR aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

None.

Reason:

A fatal accident has been reported on Elixir aeroplanes.

While the investigation is still ongoing to determine the exact cause(s) of that accident, Elixir issued Alert Service Bulletin ASB-633-005-R01, grounding all Elixir aeroplanes.

Based on all available information, EASA considers that further actions may be necessary to ensure the continued airworthiness of Elixir aeroplanes.



For the reason described above, pending the availability of more information, EASA has decided to suspend all flight operations of the affected aeroplanes.

This AD is considered to be an interim action and further AD action may follow.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

- (1) From the effective date of this AD, do not operate the aeroplane.
- (2) [RESERVED]

Ref. Publications:

None.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. The results of the safety assessment have indicated the need for immediate publication and notification, without the full consultation process.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: Elixir Aircraft, Aéroport de La Rochelle - Ile de Ré, Rue du Jura, 17 000 La Rochelle, France; E-mail: airworthiness@elixir-aircraft.com.



TRADUCTION DE COURTOISIE

de la DIRECTIVE de NAVIGABILITE de l'EASA de référence 2026-0191-E

ELIXIR AIRCRAFT

Avions
Elixir

Suspension des opérations de vol

DATE D'ENTREE EN VIGUEUR :

3 Octobre 2026

CONSTRUCTEUR(S) :

ELIXIR AIRCRAFT (ELIXIR)

APPLICABILITE :

Avions ELIXIR, tous numéros de série constructeur.

DEFINITIONS :

Les définitions suivantes s'appliquent dans le cadre de cette CN :

Néant.

RAISON :

Un accident mortel a été signalé sur des avions Elixir.

Alors que l'enquête est toujours en cours pour déterminer la ou les causes exactes de cet accident, Elixir a émis le bulletin de service d'alerte ASB-633-005-R01, interdisant de vol tous les avions Elixir.

Sur la base de toutes les informations disponibles, l'EASA estime que des actions complémentaires pourraient être nécessaires pour garantir le maintien de la navigabilité des avions Elixir.

Pour la raison décrite ci-dessus, et dans l'attente d'informations complémentaires, l'EASA a décidé de suspendre toutes les opérations de vol des avions concernés.

Cette CN est considérée comme une mesure transitoire et d'autres mesures par CN pourraient suivre.

ACTIONS ET DELAIS D'APPLICATION :

Requises telles que précisées dans cette CN, sauf si ces actions requises par cette CN ont déjà été réalisées :

(1) À compter de la date d'entrée en vigueur de cette CN, ne pas exploiter l'avion.

(2) [RÉSERVÉ]

DOCUMENTS DE REFERENCE :

Néant.

REMARQUES :

[...]